



TECHNOLOGY • QUALITY • SERVICE

Important Product Announcement - F1 EC6 EC HSW Sprinkler being Discontinued

January 2007

The F1 EC6 extended coverage horizontal sidewall sprinkler is being discontinued.

The EC6 was a UL Listed Standard Response sprinkler and NFPA 13 requires the use of Quick Response sprinklers for Light Hazard occupancies.

Reliable recommends the **F1FR QREC9 HSW sprinkler as a replacement**. The EC9 is a UL/FM Quick Response sprinkler that provides an expanded range of extended coverages for Light Hazard applications and allows installation with a deflector distance up to 12" below the ceiling.

Please see **Bulletin 148** for design and installation data on the F1FR QREC9.

If you have any questions, please contact our Technical Services Team at 1.800.55.RASCO or 864.843.5227.