

WARNING



It has been brought to our attention that in certain areas, spray foam insulation is being installed on piping to prevent freeze damage.

The foam will enter concealed sprinklers through the vent slots & prevent the sprinklers from operating.

Also, concealed sprinklers should only be installed in plenums that allow air flow through the sprinkler. The sprinklers should always be inspected after installation to insure that the gap between the cover plate and the slots in the cup are all open and free from any air flow impediments.

Any system that has had spray foam insulation installed to cover the piping must be inspected to see if the sprinklers have been compromised. Any sprinklers that are blocked from airflow must have the situation corrected.

ANY SPRINKLERS THAT HAVE FOAM BLOCKING THE SLOTS OR INSIDE THE SPRINKLER CUP MUST BE REPLACED!!